

AIR LEAKAGE: WHAT YOU SEE IS NOT WHAT YOU GET



March 10, 2016

Hannah Durschlag

Prepared for: Building Energy

COPYRIGHT



This presentation is protected by US and International Copyright laws.

Reproduction, distribution, display and use of the presentation without written permission of the speaker is prohibited.

SERVICE LINES



ENVELOPE




ENERGY



CODE ADVISORY



CONSTRUCTION
ADVISORY



ENGINEERING

COURSE DESCRIPTION



Air leakage is an important consideration in all construction. Tighter buildings are more energy efficient and comfortable. Although large buildings are rarely blower door tested, architects, enclosure consultants, manufacturers, and installers spend time and money to provide air tight buildings. Details within the contract documents and subsequent shop drawings indicate the **intended location** of the air barrier. However, over the course of mockup construction, mockup testing, and project construction, **air leakage issues often arise** that were not addressed prior, generally at unusual conditions and transitions. These locations can be difficult to detail and are typically overlooked. This presentation will first review the **basics of air leakage** detailing, and then provide specific **examples** where project documentation did not address air leakage sites, which were found in the field. Implemented field fixes will also be presented. Although project-specific, these case studies will demonstrate typical locations that must be carefully vetted during detailing.

LEARNING OBJECTIVES

At the end of the this course, participants will be able to:


1. Review the basic concepts of air leakage including measurement techniques.
2. Understand typical air barrier detailing for different construction types and transitions.
3. Review examples of typical and project-specific breaches in the air barrier, both during the drawings phase and during construction.
4. Review fixes and recommendations at these typical and project-specific breaches in the air barrier.



AIR LEAKAGE – THE BASICS

- Energy Transfer: Conduction, Convection, Radiation
- What is air infiltration? What is required for air infiltration to take place?
- What can create these conditions?


AIR LEAKAGE – THE BASICS



AIR LEAKAGE – THE BASICS

- Why do we care?
- Air leakage measurement
 - Material
 - Assembly
 - Whole building

AIR LEAKAGE – THE BASICS



How does pressure relate to air leakage?



$$Q = C \Delta P \text{ (ideal flow)}$$

$$Q = C (\Delta P)^{1/2} \text{ (turbulent flow – Bernoulli)}$$


TYPICAL DETAILING

- Curtain Wall
- Precast
- Punched windows
- Stud / knee walls


TYPICAL DETAILING - CURTAINWALL



TYPICAL DETAILING - PRECAST




A SEALANT DETAIL AT PRECAST JOINTS (PLAN OR SECTION).




B SEALANT FLASH & WEEP DETAIL AT 4-WAY INTERSECTION OF PRECAST JOINTS. (SIM. TO 3-WAY INTERSECTION.)



MOCKUP CONSTRUCTION



MOCKUP CONSTRUCTION



A SEALANT DETAIL AT PRECAST JOINTS (PLAN OR SECTION).




MOCKUP CONSTRUCTION



APPLIED ON SITE



MOCKUP CONSTRUCTION, EXAMPLE #2




MOCKUP CONSTRUCTION, EXAMPLE #2




NEW CONSTRUCTION

NEW CONSTRUCTION

Architectural




Shop Drawing







NEW CONSTRUCTION

SMOKE SEAL AT CURTAIN WALL




SMOKE SEAL AT CURTAIN WALL



SMOKE SEAL AT PRECAST

What's wrong with this solution?



5. MINIMUM 1-1/2" THICKNESS MINERAL WOOL SAFFING (MIN. 4 PCF DENSITY) COMPRESSED 33%, EXTENDING 24" ABOVE AND 12" BELOW FLOOR ASSEMBLY.

Engineering Judgement





INVESTIGATION – EXAMPLE 1

The Problem

INVESTIGATION

Two floors above the lobby






INVESTIGATION

The Exterior

INVESTIGATION

The Investigation





INVESTIGATION

The Investigation™

Conclusion

We concluded that air from the T Station and garage was moving through the exterior granite pilasters into building. The dust and dirt in the air settled on surfaces inside the office spaces above.



SOLUTIONS

Solution: Wire mesh to support spray foam insulation, followed by sprayed fibrous fire proofing.

06/10/2013 23:16



INVESTIGATION - EXAMPLE 2

The Problem: Water was pouring in above the window heads.

This problem occurred on a relatively warm day with no rain fall, after a period of cold weather.

Image by: Jeremy Moore/Flickr




INVESTIGATION



INVESTIGATION



INVESTIGATION




INVESTIGATION

Exterior Wall

- Precast concrete, with double sealed joints
- 1" airspace
- 1" mineral wool
- 1" airspace
- Steel studs with foil faced fiberglass batt
- Gypsum wall board

Any thoughts? Where is the air barrier?

Note: humidified interior



CONCLUSIONS

- The GWB was not installed as an air barrier because the sealant was not installed
- The foil-facing was not installed as an air barrier
- Interior air formed a convective loop, and moisture was deposited on the back of the concrete
- This moisture froze, then melted when the exterior temperature rose
- The water ran across the window head and pooled under the raised floor


SOLUTIONS

Possible Solutions


- Raise the temperature of the interior surface of the precast
- Eliminate movement of air flow laden with interior moisture into the wall cavity
- Align thermal, air, and vapor control layers

What do you think the client chose? What solution did we prefer?

CLIENT'S CHOICE: SALVAGED WALL



OUR CHOICE: ALIGN THE LAYERS





QUESTIONS?



THANK YOU